



Assessment Results Exceedance Table

Of the 38 samples collected at Peekskill Middle School, 1 (2.6%) had a lead concentration that exceeded 15 ppb. The table below details the sample locations and the laboratory results.

Peekskill High School				
Date	Sample ID	Floor	Location	Lead Level (ppb)
10/20/16	PMS-04	3 <sup>rd</sup>	Sink in Kitchen across from stove	31.8

Of the 106 samples collected at Peekskill High School, 46 (43.4%) had a lead concentration that exceeded 15 ppb. The table below details the sample locations and the laboratory results.

Peekskill High School				
Date	Sample ID	Floor	Location	Lead Level (ppb)
10/20/16	PHS-04	Lower	Sink in Room 301A	17.8
10/20/16	PHS-05	Lower	Left Sink in Room 300, Left Wall	10,600
10/20/16	PHS-13	Intermediate	Sink in Room 237B	21.1
10/20/16	PHS-30	Main	Sink at Teachers Desk in Room 116	65.7
10/20/16	PHS-32	Main	Center Sink in Room 116	75.1
10/20/16	PHS-38	Main	Sink in Girls Locker Room Coach Office	16.4
10/20/16	PHS-45	Main	Sink in Room 109 Teachers Desk	34.7
10/20/16	PHS-47	Main	Sink in Room 109 (Second from Left)	22.3
10/20/16	PHS-50	Main	Sink in Room 108 Teachers Desk	94.0
10/20/16	PHS-52	Main	Sink in Room 108 (Third Sink from Left)	341
10/20/16	PHS-53	Main	Sink in Room 108 (Fourth Sink from Left)	47.9
10/20/16	PHS-55	Main	Sink in Room 106 (Left)	21.2
10/20/16	PHS-56	Main	Sink in Room 106 (Second from Left)	18.4
10/20/16	PHS-57	Main	Sink in Room 106 (Third from Left)	30.7
10/20/16	PHS-58	Main	Sink in Room 106 (Fourth from Left)	29.9
10/20/16	PHS-59	Main	Sink in Room 106 (Fifth from Left)	26.1
10/20/16	PHS-60	Main	Sink in Room 106 (Sixth from Left)	30.6
10/20/16	PHS-61	Main	Sink in Room 106 (Seventh from Left)	16.7
10/20/16	PHS-62	Main	Sink in Room 106 (Eighth from Left)	38.9
10/20/16	PHS-63	Main	Sink in Room 106 (Ninth from Left)	19.8
10/20/16	PHS-64	Main	Sink in Room 106 (Tenth from Left)	20.9
10/20/16	PHS-65	Main	Sink in Room 106 (Eleventh from Left)	44.7
10/20/16	PHS-66	Main	Sink in Room 106 (Right)	163
10/20/16	PHS-69	Main	Sink in Room 104 (Second from Left)	275
10/20/16	PHS-70	Main	Sink in Room 104 (Third from Left)	173
10/20/16	PHS-71	Main	Sink in Room 104 (Fourth from Left)	21.3

Peekskill High School				
Date	Sample ID	Floor	Location	Lead Level (ppb)
10/20/16	PHS-72	Main	Sink in Room 104 (Fifth from Left)	119
10/20/16	PHS-73	Main	Sink in Room 104 (Sixth from Left)	25.9
10/20/16	PHS-74	Main	Sink in Room 104 (Seventh from Left)	16.6
10/20/16	PHS-75	Main	Sink in Room 104 (Eighth from Left)	15.2
10/20/16	PHS-77	Main	Sink in Room 104 (Tenth from Left)	21.7
10/20/16	PHS-78	Main	Sink in Room 104 (Eleventh from Left)	34.3
10/20/16	PHS-79	Main	Sink in Room 104 (Twelfth from Left)	35.0
10/20/16	PHS-80	Main	Sink in Room 104 (Right)	99.6
10/20/16	PHS-81	Main	Sink in Room 107	147
10/20/16	PHS-82	Main	Sink in Room 103 Teacher Desk	19.4
10/20/16	PHS-84	Main	Sink in Room 103 (Second from Left)	119
10/20/16	PHS-85	Main	Sink in Room 103 (Third from Left)	26.4
10/20/16	PHS-86	Main	Sink in Room 103 (Right)	24.2
10/20/16	PHS-88	Main	Sink in Room 102 (Left)	81.3
10/20/16	PHS-92	Main	Sink in Room 101 (Left)	18.2
10/20/16	PHS-94	Main	Sink in Room 101 (Right)	44.4
10/20/16	PHS-96	Main	Sink in Room 100 (Second from Left)	15.4
10/20/16	PHS-97	Main	Sink in Room 100 (Third from Left)	16.2
10/20/16	PHS-98	Main	Sink in Room 100 (Right)	52.5
10/20/16	PHS-103	Main	Prep Sink in Kitchen	114